



200171029003

24-NS-123144  
PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: Paillaman et al.

Serial No.: 10/065,516

Filed: October 25, 2002

For: METHOD OF DETECTING CRACKS IN JET  
PUMP BEAMS OF A NUCLEAR REACTOR

: Art Unit: Not Assigned

: Examiner: Not Assigned

**REQUEST FOR APPROVAL OF DRAWING CHANGE**

Commissioner for Patents  
Washington, D.C. 20231

In response to the Notice To File Corrected Application Papers, submitted herewith are two (2) sheets of drawings showing changes to the labeling of the second Figure 5 and Figure 6 in the above referenced patent application. Specifically, the second Figure 5 has been relabeled as Figure 6, and the original Figure 6 has been relabeled Figure 7.

Applicants respectfully request approval of the indicated drawing change. Also submitted are substitute drawings incorporating the above noted change.

Respectfully submitted,

  
Michael Tersillo  
Registration No. 42,180  
ARMSTRONG TEASDALE LLP  
One Metropolitan Square, Suite 2600  
St. Louis, Missouri 63102-2740  
(314) 621-5070

RECEIVED  
NOV 28 2002  
GROUP 3600



Applicant: Paillaman et al.; Serial No. 10/065,516; Atty Dkt. No. 10023144; Title: METHOD OF DETECTING CRACKS IN JET PUMP BEAMS ON A NUCLEAR REACTOR; Attorney: John S. Beulick, Armstrong Teasdale LLP, One Metropolitan Square, Suite 2600, St. Louis, MO 63102; 314-621-5070

4/5





FIG. 6



Plant: Paillaman et al.; Serial No. 10/063,516; Atty Dkt. No. 24-NS-104; Title  
METHOD OF DETECTING CRACKS IN JET PUMP BEAMS OF A NUCLEAR  
REACTOR; Attorney: John S. Beulick, Armstrong Teasdale LLP, One Metropolitan  
Square, Suite 2600, St. Louis, MO 63102; 314-621-5070

5/5




FIG. 7



4/5




FIG. 56

NOV 19 2002  
PATENT & TRADEMARK OFFICE 94C  
JCA

5/5




FIG. 7

5/5




FIG. 6

4/5




FIG. 5